SIMPLIFIED ACQUISITION PROCEDURES (SAP)

Determination Memorandum for Sole Source Acquisitions Over $3,000 but not Exceeding $150,000

SOLICITATIONS MAY BE LIMITED TO ONE SOURCE ONLY IF THE CONTRACTING OFFICER DETERMINES THAT ONLY ONE SOURCE IS REASONABLY AVAILABLE. WHEN THE CUSTOMER DESCRIBES AN ITEM OR SERVICE, WHICH LIMITS THE AVAILABILITY TO ONE SOURCE, THE DETERMINATION MUST EXPLAIN WHY THE ITEM OR SERVICE PROVIDER IS THE ONLY ONE THAT WILL MEET THE GOVERNMENT'S REQUIREMENT. STATEMENTS SUCH AS "ONLY KNOWN SOURCE" OR "ONLY SOURCE WHICH CAN MEET THE REQUIRED DELIVERY DATE" ARE INADEQUATE TO SUPPORT A SOLE SOURCE PURCHASE. THIS FORM MAY BE USED IN LIEU OF THE DETERMINATION DESCRIBED IN FAR 13.106. THE CUSTOMER SHALL PROVIDE THE FOLLOWING INFORMATION:

1. PURCHASE REQUEST OR REQUISITION NUMBER:	2. PROJECT/TASK NUMBER:	3. ESTIMATED AMOUNT: [redacted]

4. BRIEF DESCRIPTION OF SUPPLIES OR SERVICES REQUIRED AND THE INTENDED USE:

Spare Component and general maintenance of three SONY SRX S-105 projectors and MSAT Serial #002 Primary Display alignment testing at Expeditionary Warfare Training Group Pacific located at NAB Coronado in San Diego, Ca

Detailed Requirement

a. Procure the following items: 3 Lamp power supplies, 2 Power Units, 2 Lamp Inverters, 3 DC fans, 3 LPD-1 SRX panel drivers, 3 lamp combiners, 3 P/S Converters, 2 Shift Block Assemblies and 2 Lamp housings.

b. Install the SRX Panel Driver, Lamp Combiner, P/S Converter, Shift Block Assembly, Lamp Power Supply and light housings into two project

c. Test all three SRX S-105 units and adjust as required to meet factory performance specifications .

d. Mechanically Align Color across 3 projectors

e. Measure system luminance, resolution and contrast

5. UNIQUE CHARACTERISTICS THAT LIMIT AVAILABILITY TO ONLY ONE SOURCE, WITH THE REASON NO OTHER SUPPLIES OR SERVICES CAN BE USED:

Government Owned Sony Projectors requires procurement of Sony OEM ready service spares for SRX 105 Projectors. The projectors do not have substitutes in the market that can be purchased and no other designs will meet the requirement in form, fit and function. Additionally, Sony certified projector repair technicians, who are the only qualified personnel able to meet the Government's requirement, will perform minor maintenance. Multiple Sony certified vendors are available in the market. Therefore, the Government requires a brand name restriction.

6. EXPLAIN WHY AN ADEQUATE PURCHASE DESCRIPTION OR OTHER INFORMATION SUITABLE TO SOLICIT MORE THEN ONE SOURCE HAS NOT BEEN DEVELOPED:

The Sony SRX S105 Projectors require OEM Sony parts. The projector parts do not have substitutes in the market that can be purchased and no other designs will meet the requirement in form, fit and function. Therefore, the Government knows of multiple Sony resellers that it can solicit; however, only the brand name specific Sony parts can be procured.

7. PROVIDE A STATEMENT OF ACTIONS, IF ANY, THE GOVERNMENT MAY TAKE TO REMOVE OR OVERCOME ANY BARRIERS TO COMPETITION BEFORE FUTURE ACQUISITIONS ARE REQUIRED:

At each event of trainer logistic support or maintenance requirement, the items required will be identified and market research will be conducted to determine if 3rd party resources can supply necessary parts to satisfy the Government's requirement.

8. CUSTOMER		
8a. Name: [redacted]	8b. Code: [redacted]	8c. Phone#: [redacted]
8d. Signature/Date: [redacted]		
9. CONTRACTING OFFICER		
9a. Name: [redacted]	9b. Code [redacted]	9c. Phone#: [redacted]
9d. Signature/Date: [redacted]		

LKRXB105

SONY PARTS

XENON LAMP HOUSE FOR 1KW

Not Stocked

The projected shipping date of this item is 08/14/15.

1

ur Price exch)	Core Price	Total Price	Pkg Qty
[redacted]	[redacted]	[redacted]	[redacted]

A1169126A

SONY PARTS

SHIFT BLOCK ASSY (RP)

Not Stocked

The projected shipping date of this item is 08/14/15.

1

Your Price (exch)	Core Price	Total Price	Pkg Qty
[redacted]			[redacted]

urer	Description	List Price (exch)	Your Price (exch)	Core Price	Total Price	Status
TS [redacted]	OPTICAL BLOCK(RP)	[redacted]	[redacted]			

A1169110A

SONY PARTS

UNIT (RP) P/S CONVER

Not Stocked

The projected shipping date of this item is 08/25/15.

1

ir Price exch)	Core Price	Total Price	Pkg Qty
[redacted]			

A1169109A

SONY PARTS

2 LIGHT SYNTHESIS UNIT (RP)

Not Stocked

The projected shipping date of this item is 08/14/15.

1

Your Price (exch)	Core Price	Total Price	Pkg Qty
[redacted]			

rmation

ıufacturer	Description	List Price (exch)	Your Price (exch)	Core Price	Total Price	Status	Qty
IY PARTS	2 LIGHT SYNTHESIS UNIT (RP)	[redacted]	[redacted]	[redacted]	[redacted]		[redacted]

ıire original equipment parts to satisfy their warranty agreements.

Add to cart

A1087532B

SONY PARTS

MOUNTE C. BOARD LPD-1

Not Stocked

The projected shipping date of this item is 08/25/15.

1

Price (xch)	Core Price	Total Price	Pkg Qty
[redacted]	[redacted]	[redacted]	1

178733011

SONY PARTS

FAN DC (120 SQUARE)

Not Stocked

The projected shipping date of this item is 08/14/15.

1

ur Price exch)	Core Price	Total Price	Pkg Qty
[redacted]	[redacted]	[redacted]	[redacted]

178732911

SONY PARTS

FAN DC

Not Stocked

The projected shipping date of this item is 08/14/15.

1

Price ch)	Core Price	Total Price	Pkg Qty
[redacted]	[redacted]	[redacted]	[redacted]

176351821

SONY PARTS

FAN D.C.

Not Stocked

The projected shipping date of this item is 08/14/15.

1

e	Core Price	Total Price	Pkg Qty
[redacted]	[redacted]	[redacted]	[redacted]

ns

rt#:

146891012

SONY PARTS

POWER UNIT (FOR LAMP)

Not Stocked

The projected shipping date of this item is 08/14/15.

1

Image Not Availab

ation

Price (exch)	Your Price (exch)	Core Price	Total Price	Pkg Qty
[redacted]	[redacted]	[redacted]	[redacted]	[redacted]

on Information

Manufacturer	Description	List Price (exch)	Your Price (exch)	Core Price	Total Price	Status	Qty
SONY PARTS	POWER UNIT (FOR LAMP)	[redacted]	[redacted]	[redacted]	[redacted]	Not Stocked	0

rs require original equipment parts to satisfy their warranty agreements.

Add to cart

Your cart is empty

147919812

SONY PARTS

INVERTER (FOR LAMP)

Not Stocked

The projected shipping date of this item is 08/14/15.

1

rice h)	Core Price	Total Price	Pkg Qty
[redacted]	[redacted]	[redacted]	[redacted]

ation

s

t#:

146892812
SONY PARTS
POWER UNIT
Not Stocked
The projected shipping date of this item is 08/14/15.

1

tion

rice ch)	Your Price (exch)	Core Price	Total Price	Pkg Qty
[redacted]	[redacted]	[redacted]	[redacted]	[redacted]

n Information

t#	Manufacturer	Description	List Price (exch)	Your Price (exch)	Core Price	Total Price	Status	Qty
	SONY PARTS	POWER UNIT	[redacted]	[redacted]	[redacted]	[redacted]		Not Stockec

s require original equipment parts to satisfy their warranty agreements.

Add to cart

ng