

5. DEMONSTRATION OF CONTRACTORS UNIQUE QUALIFICATIONS: The current Repair Method Code (RMC/RMSC) is 3H. This acquisition will be negotiated with

Rockwell Collins INC Cage (13499). 400 Collins Rd NE. Cedar Rapids, IA 52498-0001

Only the above will be solicited because the articles to be acquired are highly specialized parts, designed and manufactured by a non-Government activity and the technical data required for repair by other than the above is not available.

6. FEDERAL BUSINESS OPPORTUNITIES/POTENTIAL SOURCES: The proposed contract was will be synopsisized in the FedBizOpps website for government wide point of entry.

7. DETERMINATION OF FAIR AND REASONABLE COST: The contracting officer determines that the anticipated cost to the Government will be fair and reasonable. In instances when certified cost and pricing data are required, an analysis of cost information will be performed which will consider field pricing reports, commerciality, procurement history and other available cost and pricing information in determining price reasonableness. Certified cost and pricing data will be obtained and used to ensure reasonableness, completeness and realism of proposed costs as required.

8. DESCRIPTION OF MARKET SURVEY: A technical review has been made to determine and identify all known sources.

9. ANY OTHER SUPPORTING FACTS:

The articles to be repaired are complex and must meet critical operational and reliability requirements, the achievement of which requires unique production techniques and extensive and/or sophisticated testing, and the government has not yet acquired or developed the technical data.

10. LISTING OF INTERESTED SOURCES: The following sources have expressed, in writing, an interest in this acquisition.

11. ACTIONS TO REMOVE BARRIERS TO COMPETITION:

NAVSUP Weapon Systems Support Source Development Department has a breakout program designed to convert as many repair acquisitions, as possible, to full and open competition. The Source Development Department has conducted a review of the available data required to support repair competition and it has been found to be inadequate. No other repair facility has the expertise, facilities or the test equipment necessary to repair the subject items other than Rockwell Collins(13499). To date, no source approval requests have been received by 0732. Future requirements will continue to be advertised in the FedBizOpps website (www.fedbizopps.gov) and in the NAVSUP-WSS repair Deficit Listing.

12. STATEMENT OF DELIVERY REQUIREMENTS:

(a) The required delivery date (month/year) is: 30 days ARO

(b) Ship To:

Various

13. REFERENCE TO THE APPROVED ACQUISITION PLAN: An Acquisition Plan is ~~not~~ required for this acquisition.

14. DOCUMENTATION FOR SPARE/REPAIR PARTS ACQUISITIONS: The specifications for the above articles have been reviewed and reflect the minimum needs of the Government.

**TECHNICAL AND REQUIREMENTS CERTIFICATION
REQUIRED BY FAR 6.303-2(b)**

I certify that the facts and representations under my cognizance which are included in this justification and which form a basis for this justification are complete and accurate.

Technical Cognizance:

[Redacted]	[Redacted]	[Redacted]	[Redacted]	[Redacted]
(Signature)	(Name and Title)	(Code)	(Phone)	(Date)

Requirements Cognizance:

[Redacted]	[Redacted]	[Redacted]	[Redacted]	11 JAN 2012
(Signature)	(Name and Title)	(Code)	(Phone)	(Date)

COMPETITION ADVOCATE REVIEW AND CONCURRENCE

[Redacted]	[Redacted]	[Redacted]	[Redacted]	FEB 02 2012
(Signature)	(Name and Title)	(Code)	(Phone)	(Date)

CONTRACTING OFFICER'S CERTIFICATION REQUIRED BY FAR 6.303-2(a)(12)

I certify that this justification is accurate and complete to the best of my knowledge and belief. (Represents approval if less than \$650K).

[Redacted]	[Redacted]	[Redacted]	[Redacted]	15 Feb 2012
(Signature)	(Name and Title)	(Code)	(Phone)	(Date)

REVIEWED FOR LEGAL SUFFICIENCY BY COUNSEL: (Over \$650K)

[Redacted]	[Redacted]	[Redacted]	[Redacted]	17 APR 2012
(Signature)	(Name and Title)	(Code)	(Phone)	(Date)

APPROVAL REQUIRED BY FAR 6.304

[Redacted]	[Redacted]	[Redacted]	[Redacted]	4/26/12
(Signature)	(Name and Title)	(Code)	(Phone)	(Date)

Approval Levels:

- Contracting Officer: Up to \$650,000
- Competition Advocate: \$650,000 to \$12,500,000
- HCA: \$12,500,000 to \$85,500,000
- ASN(RD&A): over \$85,500,000

PIIN: 1100753714

ITEM-NUM	NOMENCLATURE/ LRC/REPLACEMENT PRICE	COG/MCC/FSC/NIIN/SMIC/ PART-NUM	Total Repair Requirement (TRGT - Yrs1-5)	Repair Unit Price	Extended Repair Dollar Value
A001	CONVERTER, DIGITAL QAF [REDACTED]	7R E 7050 014110193 FW 7-151	[REDACTED]	[REDACTED]	[REDACTED]
A002	RADIO SET CONTROL G QAF [REDACTED]	7R H 5821 014375322 FW 622-8761-008	[REDACTED]	[REDACTED]	[REDACTED]
A003	CONTROL-INDICATOR QAF [REDACTED]	7R H 5895 014485023 FW 116023	[REDACTED]	[REDACTED]	[REDACTED]
A004	RECEIVER-TRANSMITT QAF [REDACTED]	7R H 5821 014563706 FW 822-1410-001	[REDACTED]	[REDACTED]	[REDACTED]
A005	CONTROL, RECEIVER-T QAF [REDACTED]	7R H 5895 014563707 EX 622-8761-009	[REDACTED]	[REDACTED]	[REDACTED]
A006	CONTROL, RADIO SET QAF [REDACTED]	7R H 5821 014646949 FW 822-1276-002	[REDACTED]	[REDACTED]	[REDACTED]
A007	RECEIVER TRANSMITT QAF [REDACTED]	7R H 5841 014726119 FW 629F11A	[REDACTED]	[REDACTED]	[REDACTED]
A008	RECEIVER-TRANSMITT QAF [REDACTED]	7R H 5821 014726124 FW 622-9887-001	[REDACTED]	[REDACTED]	[REDACTED]
A009	RECEIVER-TRANSMITT QAF [REDACTED]	7R H 5821 014726125 FW 622-9887-002	[REDACTED]	[REDACTED]	[REDACTED]
A010	CONTROL, RADIO SET QAF [REDACTED]	7R H 5821 014185207 FW 622-8761-002	[REDACTED]	[REDACTED]	[REDACTED]
A011	CONTROL, RADIO SET QAF [REDACTED]	7R H 5825 014453410 FW 622-8761-001	[REDACTED]	[REDACTED]	[REDACTED]
A012	RECEIVER-TRANSMITT QAF [REDACTED]	7R H 5821 014563702 CC 822-0383-001	[REDACTED]	[REDACTED]	[REDACTED]

Grand Total: 3,229,889.65

PIIN: 1100753714

ITEM-NUM	NOMENCLATURE/ LRC/REPLACEMENT PRICE	COG/MCC/FSC/NIIN/SMIC/ PART-NUM	Total Repair Requirement (TRGT - Yrs1-5)	Repair Unit Price	Extended Repair Dollar Value
A013	RECEIVER-TRANSMITT QAF [REDACTED]	7R H 5895 014117046 RF 622-8759-001	[REDACTED]	[REDACTED]	[REDACTED]
A014	RECEIVER-TRANSMITT QAF [REDACTED]	7R E 5821 014131812 FW 622-9878-002	[REDACTED]	[REDACTED]	[REDACTED]
A015	AMPLIFIER,RADIO FRE QAF [REDACTED]	7R H 5996 014180677 FW 822-0572-001	[REDACTED]	[REDACTED]	[REDACTED]
A016	RADIO SET CONTROL G QAF [REDACTED]	7R H 5821 014373150 FW 622-8761-006	[REDACTED]	[REDACTED]	[REDACTED]
A017	RADIO SET CONTROL G QAF [REDACTED]	7R H 5821 014375321 FW 622-8761-005	[REDACTED]	[REDACTED]	[REDACTED]
A018	RECEIVER-TRANSMITT QAF [REDACTED]	7R H 5821 014538503 FW 822-0645-005	[REDACTED]	[REDACTED]	[REDACTED]
A018 AA	RECEIVER-TRANSMITT QAF [REDACTED]	7R H 5821 014373149 FW 822-0645-004	[REDACTED]	[REDACTED]	[REDACTED]
A019	ANTENNA QAF [REDACTED]	7R E 5985 014110200 FW 12-190-6P24	[REDACTED]	[REDACTED]	[REDACTED]
A020	DIPLEXER QAF [REDACTED]	7R H 5985 014180680 FW 822-0727-001	[REDACTED]	[REDACTED]	[REDACTED]
A021	DIPLEXER QAF [REDACTED]	7R H 5985 014373108 FW 822-0970-001	[REDACTED]	[REDACTED]	[REDACTED]
A022	ANTENNA QAF [REDACTED]	7R H 5985 014726128 FW 19-440P15	[REDACTED]	[REDACTED]	[REDACTED]
A023	ANTENNA,COMMON AV QAF [REDACTED]	7R H 5895 014744520 FW 12-437-13P15	[REDACTED]	[REDACTED]	[REDACTED]

Grand Total: 3,229,889.65

PIIN: 1100753714

ITEM-NUM	NOMENCLATURE/ LRC/REPLACEMENT PRICE	COG/MCC/FSC/NIIN/SMIC/ PART-NUM	Total Repair Requirement (TRGT - Yrs1-5)	Repair Unit Price	Extended Repair Dollar Value
A024	RECEIVER-TRANSMITT QAF [REDACTED]	7R H 5821 014744521 FW 822-0645-006	[REDACTED]	[REDACTED]	[REDACTED]
A025	RECEIVER-TRANSMITT QAF [REDACTED]	7R H 5821 014951208 CC 822-1593-001	[REDACTED]	[REDACTED]	[REDACTED]
A026	RECEIVER-TRANSMITT QAF [REDACTED]	0R H 5821 015182956 CC 822-1707-001	[REDACTED]	[REDACTED]	[REDACTED]
A027	RECEIVER-TRANSMITT QAF [REDACTED]	7R H 5821 015219057 FW 822-0645-007	[REDACTED]	[REDACTED]	[REDACTED]
A028	CONTROL,RADIO SET QAF [REDACTED]	7R H 5821 015274256 FW 822-2029-001	[REDACTED]	[REDACTED]	[REDACTED]
A029	RECEIVER-TRANSMITT QAF [REDACTED]	0R H 5821 015381450 CC 822-1707-002	[REDACTED]	[REDACTED]	[REDACTED]
A030	AMPLIFIER RADIO FRE QAF [REDACTED]	7R E 5996 015383703 FW 270-2717-010	[REDACTED]	[REDACTED]	[REDACTED]
A031	RECEIVER-TRANSMITT QAF [REDACTED]	0R H 5821 015727225 CC 822-2408-001	[REDACTED]	[REDACTED]	[REDACTED]
A032	ANTENNA QAF [REDACTED]	7R H 5985 991525429 FW 19-290P23	[REDACTED]	[REDACTED]	[REDACTED]
A033	ANTENNA QAF [REDACTED]	7R H 5985 997726476 FW 12-190-6P23	[REDACTED]	[REDACTED]	[REDACTED]
A034	ANTENNA QAF [REDACTED]	7R H 5985 999217316 FW 12-190-6P46	[REDACTED]	[REDACTED]	[REDACTED]
A035	CONTROL,RADIO SET QAF [REDACTED]	7R E 5821 014373106 FW 622-8761-007	[REDACTED]	[REDACTED]	[REDACTED]

Grand Total: 3,229,889.65

PIIN: 1100753714

ITEM-NUM	NOMENCLATURE/ LRC/REPLACEMENT PRICE	COG/MCC/FSC/NIIN/SMIC/ PART-NUM	Total Repair Requirement (TRGT - Yrs1-5)	Repair Unit Price	Extended Repair Dollar Value
A035 AA	CONTROL,RADIO SET QAF [REDACTED]	7R E 5821 014110192 FW 622-8761-003	[REDACTED]	[REDACTED]	[REDACTED]
A036	CONTROL,RADIO SET QAF [REDACTED]	7R E 5821 014373106 FW 622-8761-007	[REDACTED]	[REDACTED]	[REDACTED]
A036 AA	CONTROL,RADIO SET QAF [REDACTED]	7R E 5821 014110192 FW 622-8761-003	[REDACTED]	[REDACTED]	[REDACTED]
A037	METER,ELECTRICAL FR QAF [REDACTED]	7R H 6625 014563711 FW 622-8764-002	[REDACTED]	[REDACTED]	[REDACTED]
A037 AA	METER,ELECTRICAL FR QAF [REDACTED]	7R H 6625 014440008 FW 622-8764-001	[REDACTED]	[REDACTED]	[REDACTED]
A038	RECEIVER-TRANSMITT QAF [REDACTED]	7R H 5821 014726122 FW 622-9878-004	[REDACTED]	[REDACTED]	[REDACTED]
A038 AA	RECEIVER-TRANSMITT QAF [REDACTED]	7R H 5821 014563631 FW 622-9878-003	[REDACTED]	[REDACTED]	[REDACTED]

Grand Total: 3,229,889.65