


Folder Number: 14274-0040

Requisition/PD# N0038315U0031

RMC 3. Repair, for the second or subsequent time, directly from the actual manufacturer.

RMSC B. This part must be repaired by source(s) specified on a source control or selected item drawing as defined by the current version of ASME Y14.100, Engineering Drawing Practices, Suitable technical data, Government data rights, or manufacturing knowledge is not available to permit repair by other sources. Data review discloses that required data or data rights are not in Government possession and cannot be economically obtained.

This acquisition will be negotiated with: MOOG INC (94697)




The proposed contract action was synopsisized in the FedBizOpps website for government-wide point of entry on:

21 Nov 2014

The following sources have expressed an interest in this acquisition: None

Market Research was conducted in accordance with FAR part 10. The results of the Market Research conducted (or the reason market research was not conducted) is as follows:



7. DETERMINATION OF FAIR AND REASONABLE COST: The contracting officer determines that the anticipated cost to the Government of the supplies covered by this J&A will be fair and reasonable.

8. ACTIONS TO REMOVE BARRIERS TO FUTURE COMPETITION:
For reasons set forth in Paragraph (5 & 6), NAVSUP WSS has no plans at this time to compete future contracts for the subject item covered by this document. If another potential manufacturing source emerges, NAVSUP WSS will assess whether competition for future requirements is feasible.

9. REFERENCE TO THE APPROVED ACQUISITION PLAN:
An informal / formal acquisition plan is is not required for this acquisition.