

## CONTINUATION REPORT

ICN 51KB5CORE1	KO M01	MATL ITEM ID 00850
-------------------	-----------	-----------------------

REQ DOC NO. N42158-5180Z100	REV	CONTRACT NO. N42158-	REFERENCE DOC NO.	ATTACHMENT	
NAME OF OFFEROR OR CONTRACTOR					
ITEM NO.	SUPPLIES/SERVICES	QTY	UNIT	UNIT PRICE	AMOUNT
0001	9B 6630  REPLACEMENT SERVICE  REPLACE 2 EACH EXISTING XYLEM MODEL AURORA 1030W TOC ANALYZERS IAW ATTACHED SPECIFICATIONS.	2	EA		
ACR:					

5180Z100

**TOC ANALYZERS – REPLACEMENT SPECIFICATION**

STATEMENT OF WORK:

VENDOR TO REMOVE 2 EACH EXISTING TOC ANALYZERS, REPLACE WITH NEW AURORA 1030W TOC ANALYZER KIT AND PERFORM INITIAL CALIBRATION ON THE UNITS.

KIT INCLUDES:

(2 EACH) AURORA 1030W TOC ANALYZER

(2 EACH) CD-SW-1030-ATOC-V1.4.2

(2 EACH) ENVIRONMENTAL KIT

PERIOD OF PERFORMANCE: 07-24-15 to 09-30-15

TECHNICAL POC: DANNY LUKE, (912) 573-5376

INVOICE CERTIFIER: NEIL PATTON, (912) 409-5384

LOCATION OF TOCAs: CIF, TRIDENT REFIT FACILITY, KINGS BAY, GA

THE CIF IS LOCATED IS INSIDE THE CONTROLLED INDUSTRIAL AREA. ENTRY REQUIREMENTS IN EFFECT.

PER FAR 22.102-1(A) ENTITLED "SAFETY", CONTRACTORS ARE HEREBY INFORMED THAT THEIR EMPLOYEES OR REPRESENTATIVES PRESENT ON PROPERTY UNDER NORFOLK NAVAL SHIPYARD COGNIZANCE MUST FOLLOW FEDERAL AND STATE OSHA REQUIREMENTS AND NORFOLK NAVAL SHIPYARD OSHE PROGRAM MANUAL, NAVSHIPYDNORINST P5090.2 REQUIREMENTS OR SAFETY REQUIREMENTS FOR SITE SPECIFIC LOCATION OF THE CONTRACT.