

JUSTIFICATION FOR SOLE SOURCE (UNDER \$150,000)

(Ref: NAVSUPINST 4200.85D)

REQUISITION NUMBER: N6105815RCPR018

REQUIRING ACTIVITY: Port Operations Department, Commander, U.S. Fleet Activities, Sasebo

1. Description of material: Lower Unit Assemblies for Yamaha's existing 10 Engines

- (1) Yamaha's P/N; 6CF-45300-10-8D for LF250UCA, Qty; 4 EA
- (2) Yamaha's P/N; 6CE-45300-10-8D for F250UCA, Qty; 4 EA
- (3) Yamaha's P/N; 6CF-45300-01-8D for LF225XCA, Qty; 1 EA
- (4) Yamaha's P/N; 6CE-45300-01-8D for F225XCA, Qty; 1 EA

2. Does the requested material or service represent the minimum requirement? Explain.

These required materials are minimum quantity since the required 10 lower unit assemblies are for existing 10 engines.

3. Restricted to the following source (Manufacturer's name, address, telephone number)

**Manufacturer: Yamaha Motor Corporation, USA**  
1270 Chastain Road  
Kennesaw, GA 30144  
Phone: 866-894-1264

4. Why is this requirement restricted to the proposed manufacturer? Are specifications proprietary?

Our department has Yamaha's engines for Harbor Security Boats. The proposed lower unit assemblies are suitable to the existing engines and only the unit assembly is compatible with the existing engines.

Name (type or print), Code and Phone  
Offiong, John BMC, USN CFAS OPS  
DSN: 252-2304

Shay Roadrick  
FLC Puget Sound