



DEPARTMENT OF THE NAVY
NAVAL INVENTORY CONTROL POINT

700 ROBBINS AVENUE 5450 CARLISLE PIKE - PO BOX 2020
PHILADELPHIA PA 19111-5098 MECHANICSBURG PA 17055-0788

JUSTIFICATION FOR OTHER THAN FULL AND OPEN COMPETITION

REQUISITION NUMBER/PD: N0038310YTC09

FOLDER NUMBER: _____

The format of this Justification and Approval (J&A) was reviewed and approved by NAVICP Office of Counsel. No change to the format or content of the preprinted portion of this document is allowed. Any revision to the preprinted portion of this document must be individually reviewed and approved by NAVICP Office of Counsel.

(Item Manager's Name) Please Print (Extension) 0314.21 (Code)
(Technician's Name) Please Print (Extension) 0314.51 (Code)
(Buyer's Name) Please Print (Extension) 0263.11 (Code)

1. IDENTIFICATION OF AGENCY AND/OR CONTRACTING ACTIVITY: NAVICP Philadelphia / Mechanicsburg.

2. NATURE/DESCRIPTION OF ACTION: This J&A is for the negotiation and award of a Requirements Contract through other than full and open competition. This contract will establish prices which will be valid for a period of up to 5 year(s).

3. DESCRIPTION OF SUPPLIES/SERVICES: This J&A covers the acquisition of repair/overhaul/modification and reporting effort in support of the ASN-123 system(s).

Nomen Various Quantity
NSN Varius Cage Code 06481
P/N Various Unit Price

Estimated Value (include option):

Appropriation, Subhead and Cost Code:

4. IDENTIFICATION OF STATUTORY AUTHORITY: This J&A is based upon the authority of 10 USC 2304(c)(1), as implemented by Federal Acquisition Regulation 6.302.1

5. DEMONSTRATION OF CONTRACTORS UNIQUE QUALIFICATIONS: The current Repair Method Code (RMC/RMSC) is 3H. This acquisition will be negotiated with

NORTHROP GRUMMAN GUIDANCE AND ELECTRONICS COMPANY INC. (06481)
NAVAGATION SYSTEMS DIVISION
21240 BURBANK BLVD
WOODLAND HILLS, CA. 91367 - 6675

Only the above will be solicited because the articles to be acquired are highly specialized parts, designed and manufactured by a non-Government activity and the technical data required for repair by other than the above is not available.

6. **FEDERAL BUSINESS OPPORTUNITIES/POTENTIAL SOURCES:** The proposed contract was/will be synopsized in the FedBizOpps website for government wide point of entry.

7. **DETERMINATION OF FAIR AND REASONABLE COST:** The contracting officer determines that the anticipated cost to the Government will be fair and reasonable. In instances when certified cost and pricing are required, an analysis of cost information will be performed which will consider field pricing reports, commerciality, procurement history and other available cost and pricing information in determining reasonableness. Certified cost and pricing data will be obtained and used to ensure reasonableness, completeness and realism of proposed costs as required.

8. **DESCRIPTION OF MARKET SURVEY:** A technical review has been made to determine and identify all known sources.

9. **ANY OTHER SUPPORTING FACTS:** The repairs covered by this acquisition have been continually acquired from Northrop Grumman Woodland Hills, CA, for the past 15 years, and although the requirements are recurring, NAVICP is unable to determine precise quantities required. Demand for the item(s) is subject to fluctuation. Historically, requirements for these items have been satisfied through individual procurements and/or work orders. The Contracting Officer has determined that a requirements contract will significantly reduce lead times and provide for earliest delivery of required material. The proposed contract will be written for a total period of 5 year(s), which includes a base period of 5 year(s) with no option years. The Government is obligated to place orders with the contractor for the duration of the base contractual period. Orders shall be placed as the need arises at the firm fixed prices. The Contracting Officer has concluded the award of a base contract of 5 year(s) is the best vehicle for ensuring the most advantageous price and delivery terms for meeting the Government's needs.

10. **LISTING OF INTERESTED SOURCES:** The following sources have expressed, in writing, an interest in this acquisition.

NONE

11. **ACTIONS TO REMOVE BARRIERS TO COMPETITION:** The Naval Inventory Control Point, (NAVICP), has a breakout program designed to convert as many repair acquisitions, as possible, to full and open competition. The Source Development Department has conducted a review of the available data required to support repair competition and it has been found to be inadequate. No other repair facility has the expertise, facilities or the test equipment necessary to repair the subject items other than Northrop Grumman (06481). To date, no source approval requests have been received by 0732. Future requirements will continue to be advertised in the FedBizOpps website (www.fedbizopps.gov) and in the NAVICP's Repair Deficit Listing *APB*

12. **STATEMENT OF DELIVERY REQUIREMENTS:**

(a) The required delivery date (month/year) is: 30 days ARO

(b) Ship To: XXXXXXXXXX

13. **REFERENCE TO THE APPROVED ACQUISITION PLAN:** An Acquisition Plan is not required for this acquisition.

REQUISITION NUMBER: N0036510YTC09

FOLDER NUMBER: _____

14. **DOCUMENTATION FOR SPARE/REPAIR PARTS ACQUISITIONS:** The specifications for the above articles have been reviewed and reflect the minimum needs of the Government.

PIIN: N0038310YTC09

ITEM-NUM	NOMENCLATURE/ LRC/REPLACEMENT PRICE	COG/MCC/FSC/NIN/SMIC/ PART-NUM
B001	PANEL,CONTROL,ELEC DSN [REDACTED]	7R E 1680 014287455 XE 8704721-5
B001 AA	PANEL,CONTROL,ELEC DSN [REDACTED]	7R E 1680 012423912 XE 8704721-1
B001 AB	PANEL,CONTROL,ELEC DSN [REDACTED]	7R E 1680 014287454 XE 8704721-3
B002	POWER SUPPLY DSN [REDACTED]	7R E 6130 012423813 LA 8704292-501
B003	COMPUTER,NAVIGATIO DSN [REDACTED]	7R E 6605 012426450 LA 8704302-503
B004	CONTROL-INDICATOR DSN [REDACTED]	7R E 6605 012423803 LA 8704700-503
B005	CIRCUIT CARD ASSEMB DSN [REDACTED]	7R H 5998 012423874 GL 8704770-505





DEPARTMENT OF THE NAVY
NAVAL INVENTORY CONTROL POINT

700 ROBBINS AVENUE 5450 CARLISLE PIKE - PO BOX 2020
PHILADELPHIA PA 19111-5098 MECHANICSBURG PA 17055-0788

JUSTIFICATION FOR OTHER THAN FULL AND OPEN COMPETITION

REQUISITION NUMBER/PD: N0038310YTC06

FOLDER NUMBER: _____

The format of this Justification and Approval (J&A) was reviewed and approved by NAVICP Office of Counsel. No change to the format or content of the preprinted portion of this document is allowed. Any revision to the preprinted portion of this document must be individually reviewed and approved by NAVICP Office of Counsel.

(Item Manager's Name) Please Print (Extension) 0320.16 (Code)
(Technician's Name) Please Print (Extension) 0320.T (Code)
(Buyer's Name) Please Print (Extension) 0263.11 (Code)

1. IDENTIFICATION OF AGENCY AND/OR CONTRACTING ACTIVITY: NAVICP Philadelphia / Mechanicsburg.

2. NATURE/DESCRIPTION OF ACTION: This J&A is for the negotiation and award of a Requirements Contract through other than full and open competition. This contract will establish prices which will be valid for a period of up to 5 year(s).

3. DESCRIPTION OF SUPPLIES/SERVICES: This J&A covers the acquisition of repair/overhaul/modification and reporting effort in support of the IP-1546/ASN-150 system(s).

Nomen VARIOUS (SEE ATTACHED) Quantity
NSN VARIOUSHT Cage Code 06481
P/N VARIOUS (SEE ATTACHED) Unit Price

Estimated Value (include option):

Appropriation, Subhead and Cost Code:

4. IDENTIFICATION OF STATUTORY AUTHORITY: This J&A is based upon the authority of 10 USC 2304(c)(1), as implemented by Federal Acquisition Regulation 6.302.1

5. DEMONSTRATION OF CONTRACTORS UNIQUE QUALIFICATIONS: The current Repair Method Code (RMC/RMSC) is 3H. This acquisition will be negotiated with

NORTHROP GRUMMAN (06481)

Only the above will be solicited because the articles to be acquired are highly specialized parts, designed and manufactured by a non-Government activity and the technical data required for repair by other than the above is not

available.

6. **FEDERAL BUSINESS OPPORTUNITIES/POTENTIAL SOURCES:** The proposed contract was/will be synopsised in the FedBizOpps website for government wide point of entry.

7. **DETERMINATION OF FAIR AND REASONABLE COST:** The contracting officer determines that the anticipated cost to the Government will be fair and reasonable. In instances when certified cost and pricing are required, an analysis of cost information will be performed which will consider field pricing reports, commerciality, procurement history and other available cost and pricing information in determining reasonableness. Certified cost and pricing data will be obtained and used to ensure reasonableness, completeness and realism of proposed costs as required.

8. **DESCRIPTION OF MARKET SURVEY:** A technical review has been made to determine and identify all known sources.

9. **ANY OTHER SUPPORTING FACTS:** The repairs covered by this acquisition have been continually acquired from Grumman for the past 5 years, and although the requirements are recurring, NAVICP is unable to determine precise quantities required. Demand for the item(s) is subject to fluctuation. Historically requirements for these items have been satisfied through individual procurements and/or work orders. The Contracting Officer has determined that a requirements contract will significantly reduce lead times and provide for earliest delivery of required material. The proposed contract will be written for a total period of 5 year(s). The Government is obligated to place orders with the contractor for the duration of the base contractual period. Orders shall be placed as the need arises at the firm fixed prices. The Contracting Officer has concluded the award of a 5 year contract is the best vehicle for ensuring the most advantageous price and delivery terms for meeting the Government's needs.

10. **LISTING OF INTERESTED SOURCES:** The following sources have expressed, in writing, an interest in this acquisition.

NONE

11. **ACTIONS TO REMOVE BARRIERS TO COMPETITION:** The Naval Inventory Control Point, (NAVICP), has a breakout program designed to convert as many repair acquisitions, as possible, to full and open competition. The Source Development Department has conducted a review of the available data required to support repair competition and it has been found to be inadequate. No other repair facility has the expertise, facilities or the test equipment necessary to repair the subject items other than Northrop Grumman (06481). To date, no source approval requests have been received by 0732. Future requirements will continue to be advertised in the FedBizOpps website (www.fedbizopps.gov) and in the NAVICP's Repair Deficit Listing.

12. **STATEMENT OF DELIVERY REQUIREMENTS:**

(a) The required delivery date (month/year) is: 45 DAYS ARO


(b) Ship To: XXXXXXXXXX

13. **REFERENCE TO THE APPROVED ACQUISITION PLAN:** An Acquisition Plan is not required for this acquisition.

14. **DOCUMENTATION FOR SPARE/REPAIR PARTS ACQUISITIONS:** The specifications for the above articles have been reviewed and reflect the minimum needs of the Government.

PIIN: N0038310YTC06

ITEM-NUM	NOMENCLATURE/ LRC/REPLACEMENT PRICE	COG/MCC/FSC/NIN/SMIC/ PART-NUM	HT
A001	DISPLAY UNIT YCN	7R E 7025 013667979 8900698-511	HT
A002	DATA CONVERTER,NAU YCN	7R E 6605 013667955 8901200-529	HT
A003	CIRCUIT CARD ASSEMB YCN	7R H 5998 013705769 8906460-549	HT
A004	ELECTRONIC COMPONE YCB	7R H 5998 015012814 8917600-0003	XH
A005	CIRCUIT CARD ASSEMB YCN	7R H 5998 013713987 8907450-503	HT
A006	CIRCUIT CARD ASSEMB YCN	7R H 5998 013707339 8901150-507	HT
A007	DISPLAY UNIT YCN	7R H 7025 013667964 8900730-537	HT
A008	POWER SUPPLY YCN	7R H 6130 013707256 8701205-521	HT
A009	DISPLAY,OPTOELECTR YCN	7R H 5980 014300166 2292001-6	HT
A009 AA	CONTROL-DISPLAY,OPT YCN	7R H 5980 013353215 8900691-9	HT
A010	DISPLAY UNIT YCN	7R E 7025 013667963 8900730-535	HT
A011	CONTROLLER,ARMAME YCN	7R H 1270 013667962 8900610-515	HT



PIIN: N0038310YTC06

ITEM-NUM	NOMENCLATURE/ LRC/REPLACEMENT PRICE	COG/MCC/FSC/NIN/SMIC/ PART-NUM
----------	---	-----------------------------------

A012	ANTENNA-RECEIVER-T YC	7R H 5841 014460932 HT 1072A0001-G5
A012	AA RECEIVER-TRANSMITT YC	7R H 5841 012510696 HT 1042A0001-G3
A013	CIRCUIT CARD ASSEMB YCN	7R H 5998 013356790 HT 8900530-505
A014	CIRCUIT CARD ASSEMB YCN	7R E 5998 013356788 HT 8901340-511
A015	RECEIVER-TRANSMITT YC	7R H 5841 012080512 XH 1040A0001-G53
A016	CIRCUIT CARD ASSEMB YCN	7R H 5998 013356786 HT 8901330-503
A017	CIRCUIT CARD ASSEMB YCN	7R H 5998 013356791 HT 8900680-505
A018	PANEL,INDICATING,LI YCN	7R E 6220 013433823 HT 8900690-9
A019	DISPLAY,OPTOELECTR YCN	7R H 5980 013470596 XH 8900691-19
A020	PANEL,INDICATING,LI YCN	7R H 6220 013501147 HT 8900690-11
A021	CONTROL,COMMUNICA YCN	7R E 5895 013667965 HT 8900720-521

