

JUSTIFICATION FOR SOLE SOURCE (SAP <\$150k)
Ref: FAR 13.106 and NAVSUP 4200.85D Chapter 5 Para. 2.b.(5)

The service or material listed on (Document number) 50342725 is sole source and competition must be restricted to one source, or to only one brand name for reasons indicated below. There are no substitutes available for this material.

Restricted to the following source or brand name. Provide original manufacturer's name. (If a sole source manufacturer distributes via dealers, ALSO provide dealer information.)

Manufacturer: Big Top Manufacturing
Manufacturer POC & Phone: Mr. Bobby Edwards 1-800-277-8677
Mfr. Address: 3255 N. US 19, Perry Fl. 32347
Manufacturers Dealer/Rep: Bobby Edwards
Dealer/Rep Address/Phone Number: 3255 N. US 19, Perry Fl. 32347_1-850-672-9392

Description of the item or service required, the estimated cost, and required delivery date.

Disassemble, relocate and reassemble 1 Big Top Shelter located at Bangor DLA Laydown, upper base Bangor, from the earth surface to a concrete pad constructed for it at the same site. Cost: (b) (5) Need completed by 4/1/2015.

Specific characteristics of the material or service that limit the availability to a sole source or particular brand name (unique features, function of the item, etc.). Describe in detail why only this suggested source can furnish the requirements to the exclusion of other sources.

The requested material or service represents the minimum requirements of the government

CHECK & FILL IN ALL APPLICABLE BLANKS BELOW

The material/service must be compatible in all aspects (form, fit and function) with existing systems presently installed. Describe the equipment you have now and how the new item/service must coordinate, connect, or interface with the existing system.

This tent is located at the Bangor Laydown area at upper base Bangor in a secure, locked laydown yard. The tent supports the mid and long term storage, inventory control, security and redistribution of nuclear and non-nuclear equipment to planned shipyard projects. Currently the tent cannot provide the required dry storage it was intended for because it is sitting on the bare earth and becomes filled with water and mud during the fall, winter and spring months causing material handling duties to become unsafe and causes extreme damage to equipment in some cases. It is also missing the needed 20'x20' door.

Big Top initially installed the 48'x78'x35' tent that needs to be relocated. Big Top currently warrants the tent frame. When a tent manufactured by Big Top is disassembled, it must be reassembled with all new torque bolts specific to the tent frame design to retain the structural integrity of the frame and to retain the warranty.

Should another company disassemble and reassemble the tent, the warranty will be void.

In order to create dry storage as was originally intended, a 20'x20' door needs to be installed with a manual winch to open and close the door.

In addition to the current warranty, Big Top will provide another 5 year warranty on the structure after it has been relocated and anchored to the concrete pad.

A patent, copyright, or proprietary data limits competition. The proprietary data is:

These are "direct replacements" parts/components for existing brand name equipment.
Other information to support a sole-source buy:

I CERTIFY THAT STATEMENTS CHECKED, AND INFORMATION PROVIDED ABOVE, ARE COMPLETE AND CORRECT TO THE BEST OF MY KNOWLEDGE AND DO NOT CONTAIN CLASSIFIED INFORMATION. I UNDERSTAND THAT THE PROCESSING OF THIS SOLE-SOURCE JUSTIFICATION PRECLUDES THE USE OF FULL AND OPEN COMPETITION.

Signature _____ Activity _____

Title _____ Date _____

Contracting Officer Signature

(b) (6)

Date 2/11/15

Rev 10/1/10